



Port 1



Drill all ports #50
Plug where shown
with X